Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	97228	vacuum.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/27 08:57
L2	6411	1 and plasma.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/12/27 08:57
L3	1753	2 and (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/12/27 09:14
L4	1	3 and (dry near3 etch near3 chamber).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/12/27 09:12
L5	42	3 and ( etch near3 chamber).clm.	US-PGPUB; USPAT; EPO; JPO	OŖ	ON	2005/12/27 08:59
L6	3	5 and dry.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/12/27 09:07
L7	, 5	5 and (net\$5 scren\$5 mesh\$5).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/12/27 09:08
L8	31	(dry near3 etch near3 chamber). clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/12/27 09:12
L9	1	8 and damper.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/12/27 09:13
L10	3	8 and damp\$5	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/12/27 09:13
L11	2545	damp\$4 near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/12/27 09:15

L12	1	2 and (damp\$4 near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2005/12/27 09:16
-----	---	--	---------------------------------	----	----	------------------